Site Inspection

To:	Shane Burke	**Site Inspection Number:**	SI#02
Attention:	shane@magnatechled.co.nz	**Job No:**	66865
Inspection and Report by:	SW	**Inspection Date:**	8/07/24
		Inspection Time:	3:00PM
		Issue Date:	24/07/2024
		Revision:	B

Re: Magnatech Lighting Pylon GSA 18M Pole Footing Pre-pour Inspection

Inspection Scope: Pre-pour inspection to the 18m Pole Footing

Site Progress Summary:

Reinforcement installation completed, ready for concrete pour.

#	Description/Photos	Action
1	Reinforcement installed as per the structural drawings, hold-down anchors re-installed as per the site inspection SI#01.   	No Action Needed

DISTRIBUTION: ✓ CLIENT ☐ Q.S. ☐ PROJECT MANAGER

This is NOT a variation to either the project completion date or price. If a variation is required, a separate Instruction will be issued.

Babbage Consultants Limited
128 Montreal Street, Sydenham,
Christchurch 8023
PO Box 2373, Christchurch 8140, New Zealand
T 03 379 2734 F 03 379 1642
E admin@babbage.co.nz www.babbage.co.nz